











NTERNETARRONNUMBERTARRON BOURRERA DEREN CAPTA PARRENTE ULC. RADI-BOURRORF, CREMPALINA. I DORNOLDERINARROMINI PER LABOR SE NA DA ARRON DER SANTARRON PER LIGHT DEROYADARROMENT, L'UN SOURCE CORRÀ PROGRAMMENT DER CALL



	Quick Turn Lead Time	
Layer Count	Lead Tim	Special Requirement
1L/2L	2-3days	24 Hours,48 Hours
4L	3-4days	48 Hours
6L	4-5days	72 Hours
81.	5 6days	NA NA
10L	6-7days	NA.
125.	7-8days	NA NA
14,	8-9days	NA NA
	Standard Lead Time	
Layer Count	Sample Lead Time	Volume order lead tim
2L	4 days	10 days
4L	5 days	11 days
6L	6 days	12 days
8L	8 days	14 days
10L	10 days	16 days